Compound inland flood events: different pathways–different impacts–different coping options?

Annegret H. Thieken[1], Guilherme Samprogna Mohor[1], Heidi Kreibich[2], Meike Müller[3]

[1]Institute of Environmental Science and Geography, University of Potsdam, Potsdam-Golm, 14476, Germany
[2]GFZ German Research Centre for Geosciences, Section Hydrology, Potsdam, 14473, Germany
[3]Deutsche Rückversicherung AG, Düsseldorf, 40549, Germany

Correspondence to: Annegret H. Thieken (annegret.thieken@uni-potsdam.de)

Abstract. Several severe flood events hit Germany in recent years, with events in 2013 and 2016 being the most destructive ones although dynamics and flood processes were very different. While the 2013-event was a slowly rising widespread fluvial flood accompanied by some severe dike breaches, the events in 2016 were fast onset pluvial floods, which resulted in some places in surface water flooding due to limited capacities of the drainage systems and in others, particularly in small steep catchments, in destructive flash floods with high sediment loads and log jams. Hence, different pathways, i.e. different routes that the water takes to reach (and potentially damage) receptors, in our case private households, can be identified in both events. They can thus be regarded as spatially compound flood events or compound inland floods. This paper analyses how differently affected residents coped with these different flood types (fluvial and pluvial) and their impacts while accounting for the different pathways (river flood, dike breach, surface water flooding and flash flood) within the compound events. The analyses are based on two data sets with 1652 (for the 2013-flood) and 601 (for the 2016-flood) affected residents who were surveyed around nine months after each flood, revealing little socio-economic differences–except for income–between the two samples. The four pathways showed significant differences with regard to their hydraulic and financial impacts, recovery, warning processes as well as coping and adaptive behaviour. There are just small differences with regard to perceived self-efficacy and responsibility offering entry points for tailored risk communication and support to improve property-level adaptation.

1 Introduction

Floods are the most frequent natural hazard worldwide affecting the most people (CRED and UN-DRR, 2020), with Europe being no exception (EEA, 2019). Among these, different flood types can be distinguished (de Bruijn et al., 2009):

- coastal flooding, i.e. when sea water inundates land;
- fluvial flooding, i.e. when rivers overtop their banks or embankments fail;
- pluvial flooding with areal inundations after heavy rainfall, e.g., due to limited drainage capacities.

These flood types can occur separately or simultaneously, e.g., the coincidence of coastal and fluvial flooding is commonly referred to as compound event. Originating from research on climate change, compound events are described as (1)

simultaneous or successively occurring (climate-related) events such as simultaneous coastal and fluvial floods; 2) events combined with background conditions that augment their impacts such as rainfall on already saturated soils; or (3) a combination of (several) average values of climatic variables that result in an extreme event (IPCC, 2012; Pescaroli and Alexander, 2018). However, recent inland floods revealed features of compound events. For example, severe flooding in

35   2002 caused losses of over EUR 21 billion in Central Europe (EEA, 2019). During this flood event, the city of Dresden in Saxony, Germany, was hit by four consecutive flood waves, which were all triggered by the same rainfall event: first, surface water flooding occurred in the city as an immediate response to the heavy precipitation on 12 August 2002 and the limited capacity of the sewer system, which was shortly, i.e. on the next day, followed by a flash flood from the local and mid-sized rivers Weißeritz and Lockwitzbach that drain into the bigger river Elbe within the city area of Dresden. A few

40   days later, i.e. on 17 August 2002, this flooding was followed by inundations from the flood wave of the river Elbe, which was later followed by high groundwater levels lasting for several months (Kreibich et al., 2005). Further downstream of the river Elbe, dike breaches caused huge inundations of the hinterland (DKKV, 2003). Zscheischler et al. (2020), however, termed a situation in which multiple locations are impacted within a limited time window and are connected via a physical modulator, i.e. the atmospheric circulation, spatially compound events. To avoid confusion with the coincidence of river and

45   coastal flooding, we use the term compound inland flood in this paper.

Following the source-pathway-receptor-consequences model (SPRC-model; e.g. Sayers et al., 2002), the different processes observed in Dresden and downstream in 2002 can also be regarded as specific pathways within a regional flood event, since the floodwater takes a different route to reach (and potentially damage) receptors such as buildings or residents. In flood impact analyses or loss modelling, compound inland floods with different pathways have rarely been studied although there

50   are indications that the resulting consequences differ. For example, buildings affected by dike breaches tend to experience higher losses than buildings affected by a usual river flood (Cammerer and Thieken, 2011; Mohor et al., 2020). Overall analyses of data from fluvial floods between 2002 and 2013 suggest that different flood pathways, i.e. river floods, dike breaches, surface water flooding and groundwater floods, play an important role when it comes to the assessment of (financial) flood impacts (Vogel et al., 2018; Mohor et al., 2020, 2021). Differences in coping options during the event as

55   well as in recovery in its aftermath are less clear. For example, the widespread flood of June 2013 demonstrated improved flood risk management all over Germany (Thieken et al., 2016a,b). This most severe flood event in hydrological terms (Merz et al., 2014; Schröter et al., 2015) caused lower losses, i.e. EUR 6 to 8 billion, than the 2002-flood with EUR 11.6 billion (Thieken et al., 2016a,b). Still, some areas, particularly those affected by dike breaches, suffered from severe losses. To mitigate future damage, this pathway needs further attention.

60   Next to fluvial floods, pluvial flooding has occurred in several places in Germany in recent years, e.g., in the city of Münster in 2014 (Spekkers et al., 2017) or in the village of Braunsbach in 2016 (Bronstert et al., 2018), causing damage that was unprecedented for this type of flooding. Particularly the event of May/June 2016 challenged (local) water authorities, emergency responders and residents: several places in Germany were affected by heavy rainfall and hail leading to surface water flooding due to limited capacities of urban drainage systems (GDV, 2016; Piper et al., 2016). Moreover, in some

65   places, particularly in the small towns of Braunsbach (located in the federal state of Baden-Wurttemberg) and Simbach (located in the Freestate of Bavaria), flooding was accompanied by quick concentrated surface runoff activating huge amounts of mud, debris and further material that was carried downstream, blocked culverts and threatened people and assets (Piper et al., 2016; Hübl et al., 2017; Laudan et al., 2017; LfU, 2017; Vogel et al., 2017). Overall losses amounted to EUR 2.6 billion (Munich Re, 2017), eleven people lost their lives and more than 80 people were injured, mostly by lightning

70   strokes.

Analyses of pluvial floods illustrate that warning is more difficult and residents tend to be less experienced with this flood type and are hence less prepared for it, but average property losses are commonly lower in comparison to fluvial floods (compare Kienzler et al., 2015 with Rözer et al., 2016; Spekkers et al., 2017; Kind et al., 2019; GDV, 2020). These analyses, however, mainly focussed on surface water flooding in urban areas, ignoring that impacts caused by flash floods with

75   sediment loads can be exceptionally high (GDV, 2016; Laudan et al., 2017), which was emphasized by flooding in July 2021 in Western Germany that caused more than 180 fatalities and losses of around EUR 30 billion in Germany. The severity of flash flood processes also affected mental health as well as precautionary behaviour (Laudan et al., 2020) and even led to relocations of some buildings at risk, a risk management strategy that has been rarely implemented in Germany (Mayr et al., 2020). Hence, to better understand flood impacts and coping options, it seems necessary to not only distinguish different

80   flood types (fluvial and pluvial flood), but also different pathways within one flood event, like dike breaches during fluvial floods and flash floods with sediment loads during pluvial floods.

Accounting for interactions between hazard processes helps to better understand and prepare for complex events. In this context, compound, interacting and cascading events are distinguished (e.g., Pescaroli and Alexander, 2018). We argue that the flood events of 2002, 2013 and 2016 in Germany that were described above can be understood as compound flood events

85   since rainfall from a common atmospheric circulation led to different flood situations depending on the antecedent soil moisture, the characteristics of the catchment (e.g., topography, size, land use, drainage network) and/or the failure of flood protection. Zscheischler et al. (2020) further recommend separating and analysing different elements, i.e. pathways in our view, to better understand the event as a whole. Hence, the term compound inland flood is used for floods that unfold different damaging pathways while being connected through the same triggering event.

90   Furthermore, event-oriented storyline approaches were proposed to link climate change to societal impacts in order to improve disaster risk management (Shephard et al., 2018; Sillmann et al., 2021). Therefore, we created subsamples that capture different flood pathways, i.e. dike breaches, river floods, flash floods (with sediment loads) and surface water flooding, to study their characteristics within and between the two flood events of 2013 and 2016 (see section 2 and 3.3). We hypothesize that such in-depth analyses of impact and coping patterns of different flood types and pathways provide entry

95   points to derive storylines and to better tailor flood risk management to local circumstances. In particular, this paper aims to reveal whether and how differently people were affected by different flood types and pathways, how much they were impacted in hydraulic, financial and psychological terms, and how differently they were prepared before the damaging event,

coped with it and recovered from the impacts. The intention is to provide empirically-based, quantitative insights that help establish risk management strategies tailored to different flood types and pathways.

100 Like in previous studies (Thieken et al., 2007; Kienzler et al., 2015, for fluvial floods and Rözer et al., 2016; Spekkers et al., 2017, for pluvial floods) the risk management cycle is used as guiding framework. However, in contrast to the previous studies this paper also looks at patterns within the compound inland flood events separating cases affected by dike breaches in 2013 and flash floods with heavy sediment loads in 2016 from the overall samples to better understand the impacts of and coping options towards specifically challenging pathways. For clarity, general flood types are termed fluvial and pluvial

105 floods in this paper, while pathways within the events are named dike breach, river flood, surface water flood and flash flood.

2 The compound inland floods of 2013 and 2016

2.1 The flood of June 2013

In June 2013, widespread fluvial flooding occurred in Central Europe, particularly in Germany: twelve out of 16 German

110 federal states were affected; eight of them declared a state of emergency (BMI, 2013 as cited in Thieken et al., 2016a,b). Flooding was triggered by a combination of wet antecedent conditions and high precipitation amounts between 31 May and 2 June 2013 (Merz et al., 2014; Schröter et al., 2015). By the end of May 2013, record-breaking antecedent soil moisture was recorded in 40 % of the German territory (DWD, 2013) and above-average initial streamflows were observed in many rivers (Thieken et al., 2016a). Hotspots of precipitation between 31 May and 3 June 2013 totalled up to 346 mm within 72 hours at

115 the official DWD weather station of Aschau-Stein (Schröter et al., 2015). This combination resulted in high flood peaks in the upper catchments of the rivers Rhine and Weser and particularly in many parts of the catchments of the rivers Danube and Elbe (Thieken et al., 2016a). Altogether, peak flows exceeded the five-year flood discharge in 45 % of the German river network (Schröter et al., 2015). Around 1,400 km of the river network saw 100-year flood discharges. Hydrological and statistical analyses indicated that this event was Germany's most severe fluvial flood over the past 60 years (Merz et al.,

120 2014) leading to widespread inundations, particularly along the rivers Danube and Elbe. Although huge investments had been made in upgrading embankments after the 2002-flood, some dike breaches and consequent inundations of their hinterland occurred. Three breaches were particularly severe (Merz et al., 2014): (1) a breach at Deggendorf-Fischerdorf at the confluence of the rivers Isar and Danube flooded several properties in Bavaria; due to floating and bursting oil tanks and consequently highly contaminated flood water, 150 homes had to be completely rebuilt (Bavarian Parliament, 2014); (2) a

125 breach in Klein Rosenburg-Breitenhagen at the confluence of the rivers Saale and Elbe in Saxony-Anhalt and (3) a breach near Fischbeck at the middle reach of the Elbe River in Saxony-Anhalt that also affected the high-speed train connection between Berlin and Hanover which was disrupted for several months (Thieken et al., 2016b). In all of Germany, 14 people died and direct losses summed up to EUR 8 billion (Thieken et al., 2016b).

In comparison to regions flooded by a river, areas affected by dike breaches tend to suffer from extended inundation durations (Vogel et al., 2018) and – where oil heating is common – floating and leaking oil tanks that cause considerable material and environmental damage (DKKV, 2015; Thieken et al., 2016b). Considering the triggering mechanism of this flood, as well as the dike breaches mentioned above, this event can be understood as a spatially compound event. To account for different flood pathways, residents affected by "normal" river floods and residents affected by dike breaches are analysed separately in this paper.

2.2 Flooding in May and June 2016

From May 26 to June 9, 2016, Germany and parts of central and southern Europe were hit by an extraordinarily high number of severe convective storms with intense rainfall and hail. This thunderstorm episode was caused by the interaction of high atmospheric moisture content, low thermal stability, weak wind speed and large-scale lifting by surface lows (Piper et al., 2016). Low wind speed at mid-tropospheric levels led to nearly stationary or slow-moving convective cells and hence to locally extreme rain accumulations exceeding 100 mm within 24 hours. Due to atmospheric blocking these boundary conditions persisted for almost two weeks (Piper et al., 2016). Depending on the characteristics of the affected catchments and areas the heavy precipitation triggered surface water flooding (due to limited sewer capacity, e.g. in the city of Hanover in Lower Saxony), inundations along (small) rivers and creeks and flash floods, partly carrying huge amounts of mud and debris. The main hotspots occurred in South Germany. In Braunsbach, a small village in Baden-Wuerttemberg, the extreme precipitation of more than 100 mm within 2 hours on May 29 caused a devastating flash flood (Bronstert et al., 2017). The Orlacher Bach, a creek that runs through the village with just 6 km² catchment size and very steep slopes, showed extreme runoff with massive debris transport of 42,000 m³ (Vogel et al., 2017). Streets were blocked with gravel and stones up to a thickness of 2 to 3 m producing immense damage to buildings and infrastructure (Laudan et al., 2017). In Simbach, a village in south Bavaria, situated on the river Inn, the rainfall amounted to 120 mm in 24 hours on June 1 (Pieper et al., 2016). Subsequently the small river Simbach (33 km² catchment size) and its tributaries showed extreme runoff. At the gauging station Simbach the water level rose from 50 cm to 506 cm within 14 hours. Several culverts were blocked with debris and driftwood, dams broke and parts of the village were flooded (LfU, 2017).

In all of Germany eleven people died and the economic loss amounted to EUR 2.6 billion which is extraordinary high with regard to heavy rainfall and thunderstorms in Germany (GDV, 2016; Laudan et al., 2017; Munich Re, 2017; Vogel et al., 2017). Because of the huge losses in Simbach and other villages in Bavaria a grant and loan programme for compensating flood damage to residential buildings and household contents was implemented (Bavarian State Government, 2016). In Baden-Wurttemberg, the market penetration of insurance against natural hazards is still high, i.e. around 94 %, due to the fact that it was mandatory until 1994 (Surminski and Thieken, 2017; GDV, 2020).

Since different types of flooding and various runoff dynamics could be observed from May 26 to June 9, this event is also treated as a spatially compound inland flood in this paper. The dynamics comprise different pathways, flow velocities, water depths as well as different impacts that are difficult to categorise distinctly. Yet, households have been mainly affected by

shallow surface water flooding, but, in fewer cases, also by the forceful overflowing of water bodies and partly log jams and subsequent dam breaches which led to strong flash floods with a heavy sediment load (e.g. in Braunsbach and Simbach). Thus, the data set from this pluvial flood was separated into cases affected by low/medium surface water flooding on the one hand and cases that suffered from flash floods with debris flows on the other hand (Figure 1; see section 3.3 for details).

Figure 1: Geographic overview of the number of households surveyed about the flood of 2013 (left) and 2016 (right).

3 Data and Methods

The analyses are based on survey data that were gathered among private households that suffered from property damage caused by flooding in 2013 or 2016. Both surveys were conducted around nine months after the respective damaging event using computer-aided telephone interviews (CATI), during which residents were guided through a standardized questionnaire (see Thieken et al., 2017). On average, an interview lasted around 30 minutes.

3.1 Sampling flood-affected households

To identify affected households, media reports and satellite images were used to compile a list of inundated streets and zip codes. In some cases, this information was provided by affected communities and districts or fire brigades. The lists served as a basis for retrieving telephone numbers (landlines) from public telephone directories. Due to a high number of non-affected residents within the areas identified, all retrieved telephone numbers were finally called. Always the person in the household who had the best knowledge about the flood event was questioned. The surveys were conducted by a subcontracted pollster from 18 February to 24 March 2014 for the 2013-flood and from 28 March to 28 April 2017 for the 2016-event. In total, 1652 interviews from 173 different municipalities across nine federal states were completed for the 2013-flood (out of a total of 43,281 numbers, from which 16,554 could not be reached during the field time; another 16,721 residents did not suffer from financial damage and 8144 refused to participate). For the 2016-event, it was possible to complete 601 interviews in 76 different municipalities spread across nine federal states of Germany (out of 42,487 retrieved numbers, from which 24,486 could not be reached during the field time; 12,010 residents did not suffer from financial damage and 4254 refused to participate).

3.2 Contents of the questionnaire and data processing

The questionnaires already presented by Thieken et al. (2005; 2007) and Rözer et al. (2016) were slightly adapted for the two surveys and contained about 160 questions addressing a range of topics: source of flooding (pathway), depth, velocity and duration of the inundation at the affected property, contamination of the flood water, flood warnings, emergency measures, characteristics of and amount of damage to household contents and buildings, recovery and psychological burden of the interviewed person, precautionary measures, previously experienced flood events, perceived threat and coping appraisal, as well as socio-demographic information. In both surveys, tenants were only asked about their household, the damage to contents and some core characteristics of the building. Several questions used an ordinal Likert-type scale from 1 to 6, where just the meanings of the end points were explicitly verbalized to enable quantitative analyses.

After the collection, data was post-processed through comparisons and consistency checks. While questions about characteristics of the building, e.g., the existence of a cellar, and the type of the losses were cross-checked during the survey, additional checks were performed in the aftermath, e.g., the size of the household was compared to the reported numbers of children and elderly in that household. In addition, some items were aggregated to indicators as described by Thieken et al. (2005) and Laudan et al. (2020): contamination, source of the flood warning, emergency measures (short-term; performed during the event), precautionary measures (long-term measures, implemented before or after the flood) and previously experienced flooding.

Further, the total asset values of contents and buildings were estimated based on the floor space (of the flat or the building) and standardized values. For contents, a unit value of 650 EUR/m² as of 2005 was scaled to the year of the event by a consumer price index excluding food, resulting in 695.90 EUR/m² (as of 2013) and 719.52 EUR/m² (as of 2016). The total

205 value of a building was estimated by the "Mark1914"-insurance value per m² per building type multiplied by the "Gleitender Neuwertfaktor" (16.2 for 2013 and 17.2 for 2016), a specific building price index used by the German insurance industry. If the reported damage exceeded the so-estimated asset value, a loss ratio of 1 was assumed. For the comparisons in this study, all monetary values of 2013 were scaled to 2016 based on price indices.

3.3 Subsamples

210 To study differences in flood pathways the following subsamples were distinguished (compare Figure 1):

- 2013-dike breaches: all households that reported that they had been affected by a dike breach were included in this subsample; this applied to 394 cases from more than 60 different places across six federal states, i.e. to around 24 % of all surveyed cases affected by flooding in 2013;

- 2013-river flooding: all other households from the 2013-data set, i.e. 1258 cases (76 %) located in more than 160
215 municipalities across nine federal states;

- 2016-flash floods: all surveyed households from areas that had been affected by severe flash floods accompanied by sediment loads, log jams or failure of flood protection (see below); this applied to 153 cases from ten different municipalities located in three different federal states, i.e. to around 25 % of all surveyed cases affected by flooding in 2016;

220 - 2016-surface water flooding: all other households from the 2016-data set, i.e. 448 cases (75 %) from 66 different municipalities across nine federal states.

The places of cases that reported dike breaches in the 2013-survey were cross-checked with the three locations of severe levee breaches (see introduction), revealing that at least 74 cases can be linked to the breach at Deggendorf-Fischerdorf, 129 to the breach in Klein Rosenburg-Breitenhagen and 62 to the breach near Fischbeck (Elbe) illustrating that the answers of the
225 respondents are credible.

Since different pathways of the pluvial flooding in 2016 were more difficult to be distinguished by lay people and were not well captured by the survey questions on the damaging flood pathways, event analyses and reports were used to identify places that were hit by rapid onset floods that were accompanied by huge sediments loads, debris flow, log jams and/or failure of flood protection. Such event characteristics were described for the municipality of Braunsbach in Baden-
230 Wurttemberg (e.g. Laudan et al., 2017; Bronstert et al., 2018) as well as for Künzelsau und Forchtenberg based on field inspections (Mühr et al., 2016). In Bavaria, similar damaging processes were described for the municipalities of Ansbach, Flachslanden, Julbach, Obernzenn, Simbach, and Triftern (Hübl et al., 2017; LfU, 2017). An overtopped flood retention basin was reported for the municipality Grafschaft in Rhineland-Palatinate (Demuth et al., 2016). All cases from these municipalities were included in the flash flood sample.

235

3.4 Data Analysis

Data subsets were compared either through the nonparametric Mann-Whitney-Wilcoxon two-sample test or Chi-Squared contingency table test, depending on whether a variable was metric or categorical (Noether, 1991), comparing the median of differences or the closeness of expected frequencies, respectively.

240 A p-value threshold was set to 0.05 for statistical significance, regardless of the absolute difference or effect size. These procedures were run with R language (R Core Team, 2017) – with the assistance of the packages "stats", "rcompanion", and "PMCMR". For variables with significant differences further statistics were calculated in SPSS. Means and frequencies are presented in relation to the valid answers, i.e. ignoring no answers or "I don't know" entries.

4 Results and Discussion

245 In this section we present the main differences and commonalities between and within the two compound inland flood events. Per topic we will first compare the fluvial 2013-flood to the pluvial 2016-flood, which is then followed by a comparison of the flood pathways within each compound event, i.e. river floods versus dike breaches for the 2013-event as well as surface water floods versus flash floods in 2016.

4.1 Socio-demographic characteristics of the subsamples

250 This section presents the characteristics of the surveyed residents in the four subsamples. Besides the mean values for each item and each subsample as well as for the whole data set, Table 1 provides the test statistics of the Mann-Whitney-Wilcox or Chi-Square tests when comparing all data from the 2013-flood with the 2016-flood as well as when comparing the two subsamples (pathways) within each event.

On a 5%-significance level, Table 1 reveals that socio-demographic characteristics do not differ between the two events,
255 except for the share of households with a monthly net income below EUR 1500 and the share of one-family homes. Both values are higher for the 2013-flood, reflecting that more rural areas were affected by this widespread fluvial flood. Those affected by surface water flooding in 2016 had the smallest percentage of households with income below EUR 1500 or, in other words, a higher share of higher-income households than the other subsamples, as well as the smallest percentage of households living in one-family homes reflecting that mainly urban areas were affected by this flood pathway. In contrast,
260 the flood of 2013 widely affected rural areas in the Eastern parts of the country. The 2013-sample contains many cases from Saxony and Saxony-Anhalt (see Fig. 1); in East Germany the mean monthly net income per household amounted to EUR 2521 in 2013, while it was EUR 3297 in West Germany that was hit by the 2016-floodings (Destatis, 2018; see Fig. 1). So, the differences in income in our data reflect the regional income pattern in Germany.

In addition, there are slight (i.e. low-significant) differences between the two events with respect to the mean household size
265 and homeownership (Table 1). However, these variables differ more pronounced between the two subsamples of the 2013-flood: surveyed households affected by river flooding had the smallest household size and the lowest percentage of

home/apartment ownership (80 %), whilst those affected by dike breaches showed the highest percentage of homeowners (92 %). Similarly, the 2013-river subsample shows a lower share of one-family homes (51 %) than the 2013-dike subsample (71 %). This suggests that areas affected by dike breaches were mostly rural areas with owner-occupied dwellings and larger families, while other areas affected in 2013 are probably located in more urban settings, also showing a better education and a higher mean age. Similar, but statistically weaker differences were found for the 2016-event. Here the regions affected by flash floods slightly tend to contain more one-family homes, a lower age and less people with a high-school graduation than areas affected by surface water flooding. Still, there are no significant differences in the living area per person among the subsamples, despite a range between 55 m² (river floods) and 64 m² (flash floods). Often, the flash flood subsample did not show high statistical differences to other subsamples, even when presenting the highest or smallest means due to its smaller number of cases (Table 1).

Table 1: Socio-demographic characteristics of households affected by different flood pathways in 2013 and 2016.

Subsample (Pathway)	River2013	↔	Dike2013	2013 ↔ 2016	Surface2016	↔	Flash2016	Overall
Sample size	1258	—	394	—	448	—	153	2253
Socio-economic and demographic variables								
Female interviewee [%]	59.1		55.3		58.0		53.6	57.8
Mean age of the interviewees [years]	60.4	****	57.1		59.2	.	57.1	59.3
People with high school graduation (*Abitur*) [%]	34.9	**	27.4		36.1	*	24.1	33.1
Mean household size [number of people]	2.4	****	2.7	.	2.6		2.7	2.5
Households with a monthly net income <1500 Euro [%]	35.6		35.4	****	15.9		20.6	30.3
Mean living area per person [m²]	55.1		58.0		60.4		64.4	57.5
Homeowners (house or apartments) [%]	79.7	****	92.1	.	85.9		86.3	83.6
One-family homes [%]	50.9	****	71.0	****	39.5	.	49.0	52.1

Percentage or means only regarding valid values, i.e. answered entries.

Comparison of subsets or 2013 to 2016 in the middle columns, with P-value ranges from Mann-Whitney-Wilcox or Chi-Square tests represented as: Legend: '****' ≤0.001 '***' ≤0.005 '**' ≤0.01 '*' ≤0.05 '.' ≤0.1 ' ' ≤1

Altogether, the characteristics of the four subsamples lie within previous studies' averages, though with varied sample sizes and from different regions in Germany, which should be taken into account when interpreting further results. Previous works compared the socio-economic characteristics of survey respondents to a city or a national census. Some differences are noticeable such as a higher age and a greater share of ownership among respondents, probably because only fixed landlines

were consulted. Given the similarity of sampling methods, we expect similar biases in all sub-samples. For a more detailed discussion of potential biases, see the works of Kienzler et al. (2015), Rözer et al. (2016) and Spekkers et al. (2017). Nevertheless, all sub-samples contain data from several municipalities and federal states reflecting different geographic,

290 social and governance contexts across Germany. Even the smallest sub-sample of the flash floods contains 153 cases from ten municipalities located in three different federal states (Figure 1) allowing us to draw conclusions beyond the studied events in Germany.

4.2 Flood characteristics

The hydraulic impacts of the flood events on the affected buildings are presented in Table 2 in terms of water level, flood

295 duration, flow velocity, and the presence of contamination by oil, which all differ significantly between the events of 2013 and 2016 as well as within the two events (except for flow velocity in the case of the 2013-flood). There is a clear difference in water level from surface water floods, which mostly affected only the cellar of houses (indicated by negative values in Table 2), followed by river floods to cases of dike breaches and flash floods, which showed the highest mean water level. Negative average water levels, i.e. a water level below the ground surface, were also reported for pluvial and fluvial floods in

300 2005 (Rözer et al., 2016; Kienzler et al., 2015), a frequent river flood in 2011 (Kienzler et al., 2015) and the Danube area affected in 2002 (Thieken et al., 2007). Hence, the mean water level roughly reflects the intensity of the event.

Surface water and flash floods have considerably shorter durations than river floods and dike breaches (Table 2). This pattern is also noticed by Kienzler et al. (2015), given that floods in 2002, 2006 and 2011 with an average duration of more than four days had a predominance of riverine flood dynamics, whilst Rözer et al. (2016) found shorter durations, less than

305 one day in average, for pluvial floods. This pattern of the pathways is reflected in our samples roughly confirming the approaches how the subsamples of the pathways were created.

Of those who were affected by river floods or dike breaches only around 15 % reported a very high water velocity, i.e. a value of 5 or 6 on a scale from 1 to 6, in contrast to 65 % in case of flash floods and 28 % in case of surface water floods. The percentage of cases that reported oil contamination was the lowest in surface water floods (3 %), followed by river

310 floods (12 %) and the flash flood subsample (24 %). The highest value (34 %) was reported by residents who were affected by dike breaches (see Table 2). A similar pattern is revealed for other contaminants like sewage, chemicals or petrol (Figure 2).

Altogether Table 2 illustrates that the people affected by different flood pathways had to cope with significantly different hazard situations, particularly in terms of water levels, flood duration and oil contamination. In addition, residents affected in

315 2016 by flash floods had to cope with high flow velocities. These findings confirm that our subsamples represent significantly differing flood pathways, while their socio-demographic characteristics differ comparatively little (see section 4.1). The next section looks into the financial flood impacts and recovery before we address coping options and strategies.

Table 2: Hydraulic flood characteristics and impacts reported by households affected by different flood pathways in 2013 and 2016.

Subsample (Pathway)	River2013	↔	Dike2013	2013 ↔ 2016	Surface2016	↔	Flash2016	Overall
Sample size	1258	—	394	—	448	—	153	2253
Mean water level above top ground surface [cm]	46.4	***	76.3	****	-112.8	****	82.8	23.7
Mean flood duration [hours]	173	****	312	****	41	****	36	164
Cases [%] that reported very high flow velocity, i.e. 5 or 6 on a scale from 1= no flow to 6 = very high velocity/ turbulent flow	15.2		15.5	****	28.5	****	65.5	21.1
Cases that reported oil contamination [%]	12.2	****	34.3	****	2.7	****	24.2	15

Percentage or means only regarding valid values, i.e. answered entries.

Comparison of subsets or 2013 to 2016 in the middle columns, with P-value ranges from Mann-Whitney-Wilcox or Chi-Square tests represented as: `Legend: '****' ≤0.001 '***' ≤0.005 '**' ≤0.01 '*' ≤0.05 '.' ≤0.1 ' ' ≤1`

Figure 2: Contaminants in the flood water as reported by households affected by different flood pathways in 2013 and 2016 (multiple answers possible).

4.3 Financial flood impacts and perceived recovery

The average financial losses of buildings and household contents differ significantly between and within the flood events (Table 3). Here, the financial loss refers to the repair and replacement costs (in prices of 2016). Residents affected by flash floods suffered from the highest financial losses – in absolute numbers as well as in terms of loss ratios, followed by those affected by dike breaches and river floods. Losses caused by surface water flooding resulted in the lowest amounts (in absolute numbers as well as with regard to loss ratios; see Table 3). Overall, the significant differences in the flood processes and the resulting hydraulic loads presented in Table 2 are reflected in the adverse effects of the floods.

To capture the status of recovery at the time of the survey, i.e., 8 to 10 months after the damage occurred, payments received to compensate losses were recorded. Further, respondents were asked to assess the accomplishment of the replacement of damaged household items or of the repair works at the damaged building on a Likert-scale. On a similar scale, they were asked to assess the psychological burden the flood still had at the time of the survey. Table 3 reveals that all variables except for the perceived status of the replacement of damaged household items significantly differ between 2013 and 2016. In addition, there are highly significant differences between the pathways within the two events. In general, respondents affected in 2016 received higher pay-outs, assessed their recovery a bit better and felt less burdened than those affected in 2013. However, those who experienced a flash flood in 2016 recovered less and felt more burdened than those affected by surface water flooding. Similarly, residents affected by dike breaches in 2013 are worse off than those affected by river flood.

Table 3: Financial flood impacts, perceived recovery and psychological burden reported by households affected by different flood pathways in 2013 and 2016.

Subsample (Pathway)	River2013	↔	Dike2013	2013 ↔ 2016	Surface2016	↔	Flash2016	Overall
Sample size	1258	—	394	—	448	—	153	2253
Financial damage								
Mean financial damage to the building [EUR] (1)	48,610	****	81,910	****	17,650	****	123,000	56,140
Mean financial damage to the contents [EUR] (1)	16,220	****	27,830	****	12,350	****	47,400	20,700
Mean loss ratio of the building [%]	9.4	****	17.0	****	3.3	****	21.0	11
Mean loss ratio of the contents [%]	19	****	29.9	****	10.7	****	38.6	22
Perceived recovery AT THE TIME OF THE INTERVIEW, i.e. 8 to 10 months after the damaging flood event								
Mean loss compensation (payouts) [EUR] (1)	10,810	****	18,200	****	16,680	****	33,110	14,320
Mean perceived status of repair works at the building [Likert-scale from 1 (building is completely restored) and 6 (there is	2.8	****	3.3	****	1.7	****	2.9	2.6

still considerable damage)]							
Mean perceived replacement of damaged household items [Likert-scale from 1 (damaged household items are completely replaced) and 6 (still considerable missing household items)]	2.4	****	3.0	.	2.1	****	3.2	2.6
Mean perceived psychological burden [Likert-scale from 1 (no burden at all) to 6 (still heavy burden)]	3.4	****	4.0	****	2.6	****	3.7	3.3

Percentage or means only regarding valid values, i.e. answered entries.

(1) in 2016-prices

350

Comparison of subsets or 2013 to 2016 in the middle columns, with P-value ranges from Mann-Whitney-Wilcox or Chi-Square tests represented as: `Legend: '****' ≤0.001 '***' ≤0.005 '**' ≤0.01 '*' ≤0.05 '.' ≤0.1 ' ' ≤1`

Altogether, the recovery status around nine months after the damaging event is worse for households affected by the stronger

355 pathways, i.e. dike breaches in 2013 or flash floods in 2016, compared to the low/medium pathways, i.e. river floods in 2013 or surface water floods in 2016. It should be noted that the financial damage was the most severe for flash floods, while the psychological burden and the perceived recovery were the worst for residents who experienced dike breaches in 2013, who are then followed by the flash flood cases (Table 3). Maybe the better recovery among severe cases in 2016 is owing to the stronger community resilience that was found to buffer psychological burden in Simbach and surroundings (Masson et al., 2019) as cases from Simbach constitute almost 37 % of this subsample (57 of 153 cases). Therefore, this finding needs more

360 cases studies for a confirmation. Furthermore, it is striking that the average pay-outs for loss compensation are – in relation to the mean financial losses – considerable higher for the cases affected by the 2016-floods in comparison to the 2013-flood. Again, this could be due to the local specifics, e.g. the high insurance penetration in Baden-Wurttemberg (GDV, 2020) and the compensation programme in Bavaria (Bavarian State Government, 2016).

In general, financial losses, recovery and psychological burden show highly significant differences between the two events

365 as well as between the pathways. Financial impacts and recovery tend to follow the severity pattern of the flood characteristics (i.e. the hydraulic impact variables shown in Table 2), particularly the water level, which is considered the most important variable that explains flood damage (e.g. Gerl et al., 2016; Vogel et al., 2018). Within each flood event, the stronger flood pathway, i.e. dike breaches and flash floods, show significantly higher values than their less severe counterparts (river and surface water floods). This supports the hypothesis that the overall (hydraulic) severity of a flood

370 pathway is more important for the perceived psychological burden than the general flood type (see Laudan et al., 2020). The results further support studies that recommend developing pathway-specific loss models (Vogel et al., 2018; Mohor et al., 2020, 2021). At this point, the question arises whether and to which degree flood pathways also govern coping options.

4.4 Short-term response as coping strategy: warning and emergency measures

There are several strategies to mitigate flood impacts, of which 1) preparedness and response in the case of an event, 2) damage mitigation by implementing property-level adaptation measures and 3) risk transfer in terms of insurance coverage are the most relevant for residents (Driessen et al., 2016). The first strategy can also be described as reactive or short-term response, while the second is seen as a more proactive or long-term coping strategy (Neise and Revilla Diez, 2019). Insurance coverage does not primarily reduce damage, but facilitates a quick recovery since financial losses are compensated; its interlinkage with property-level adaptation is not clear (e.g. Surminski and Thieken, 2017; Hudson et al., 2017, 2020). In this section, we focus on reactive responses, for which timely warning is an important pre-requisite (e.g. Penning-Rowsell and Green, 2000).

Table 4 reveals highly significant differences between the two flood events with regard to warning and emergency response. Residents affected by the 2013-flood were warned more often and at a considerably longer lead time in comparison to the 2016-event (Table 4). After the extreme flood event in 2002 in Germany, various initiatives and high investments had been undertaken to improve river flood risk management including early warning and preparedness, which had proven to be successful in 2013 (Thieken et al., 2016a; Kreibich et al., 2017).

Table 5 provides more details on how people had become aware of the imminent flood danger underlining the huge differences between the two flood events. Considerably more residents who had been affected by the 2013-flood received official flood warnings than it was the case in 2016: while 31 to 55% of the people affected in 2013 were warned by severe weather warnings, flood alerts or calls for evacuation, this applies to just 3 to 14 % of those affected in 2016 (Table 5). It is striking that own/independent observations play an important role in all four data subsets: one third to more than half of the people per subsample reported that their own observations of e.g. cloud formations, heavy rainfall or rising water levels made them aware of the imminent flood danger (Table 5). However, while just 4 to 6% of the 2013-flood victims were not warned at all, this applies to 26 to 36% of people surveyed in 2016 (Table 4 and 5).

These numbers reflect the current differences in the warning capabilities of river floods and convective storms or flash floods: while river floods, particularly at reaches downstream, can be forecasted several days in advance, forecasting convective storms that cause pluvial flooding is more challenging due to the dynamic formation of convective cells. Moreover, small creeks are often ungauged and not included in the regional flood monitoring and forecasting system of the federal state, but may unfold unexpected flash floods and inundations. Hence, lead times are restricted to a few hours, if at all (Merz et al., 2020). This is illustrated by the average lead time that is particularly short for the flash floods in 2016 (Table 4). The median values suggest that 50% of the people affected in 2013 were warned at least 24 hours before the water entered their home, while this value drops to just one hour for the 2016-subsets (Table 5), which contain maximum lead times of 24 hours in the surface water subset (20 cases from 14 different places) and maximum lead times of 12 hours in the flash flood subset (3 cases from 3 different places). For the pathway dike breach, which is characterized by stronger and unforeseen flooding, the mean lead time is significantly different from the mean value for river floods (Table 4), indicating

that dike breaches pose an additional challenge on timely and informative warnings and hence time-critical situations may arise in the hinterland of dikes. The fact that the percentages of people who were not warned and – to a lesser degree the lead time – do not differ (highly) significantly between the flood pathways, but between the events underlines that warning possibilities and capacities are primarily governed by the overall flood type (fluvial versus pluvial) or the triggering

410 atmospheric pattern, while knowledge and emergency response are additionally influenced by the pathway, particularly in 2013 (Table 4).

Table 4: Characteristics of the warning process and emergency response as reported by households affected by different flood pathways in 2013 and 2016.

Subsample (Pathway)	River2013	↔	Dike2013	2013 ↔ 2016	Surface2016	↔	Flash2016	Overall
Sample size	1258	—	394	—	448	—	153	2253
Households that received no warning [%]	6.3		4.3	****	35.5	*	25.5	13.1
Mean warning lead time [hours][1]	36.5	*	30.4	****	2.5		1.2	27.6
Mean perceived knowledge about self-protection [Likert scale from 1 (I knew exactly what to do) to 6 (I did not know at all what to do)]	2.4	****	3.1	****	4.3	*	4.8	3.1
Average number of performed emergency measures [count]	4.24	***	4.64	****	1.65		2.00	3.64

415 [1]: *Cases that received no warning were considered with a lead time of 0 hours.*

Comparison of subsets or 2013 to 2016 in the middle columns, with P-value ranges from Mann-Whitney-Wilcox or Chi-Square tests represented as: Legend: `'****' ≤0.001 '***' ≤0.005 '**' ≤0.01 '*' ≤0.05 '.' ≤0.1 ' ' ≤1`

Residents affected by river floods in 2013 knew much better how to protect themselves from flooding than people affected in

420 2016 (Table 4). In addition, the values of the perceived response knowledge indicate highly significant differences within the event of 2013, suggesting that people affected by dike breaches had to cope not only with shorter lead times, but were more often unaware of what they could do to mitigate losses and protect their lives. Knowledge about adequate behaviour is, however, an important pre-requisite for loss mitigation (Kreibich et al., 2021). Within the 2016-event differences are smaller, but indicate that people affected by flash flood were less informed/prepared (Table 4). In detail, the percentage of well-

425 informed people who chose a 1 or 2 when asked how well they knew how to protect themselves and their household from flood impacts on a scale from 1 to 6, drops from 65 % for river floods in 2013 to 48 % in the subset containing dike breaches and even to 24 % of cases with surface water flooding in 2016 and 15 % for flash floods in 2016. This pattern indicates shortcomings in crisis and risk communication with respect to pluvial flooding in general and flash floods in particular, but it could also be influenced by previously experienced flooding and associated learning effects (see section 4.6).

430   The different warning capabilities and the different levels of perceived response knowledge are further reflected in the responsive behaviour during the events: residents affected in 2013 undertook a significantly higher number of emergency measures namely around four or five, than those affected in 2016 with one or two measures on average, while there are no differences between pathways in 2016 (Table 4).

435   **Table 5: Answers to the question: "How did you become aware of the imminent danger of being flooded?" (multiple answers possible), given in percentage of all interviewed residents per subset and median lead time per subset.**

Subset	2013-river flood	2013-dike breach	2016-surface water flood	2016-strong flash flood
Severe weather warning (by DWD)	44.0%	31.0%	13.6%	9.2%
Severe weather warning (by other agencies)	---	---	3.3%	6.5%
Flood warning by authorities	44.7%	50.0%	---	---
Warning and evacuation at the same time	25.5%	54.8%	---	---
General media coverage	16.8%	18.5%	5.4%	1.3%
Warning by neighbours, friends etc.	17.7%	19.0%	7.6%	11.8%
Own independent search for information	27.8%	24.9%	2.0%	0.7%
Independent observations (e.g. water levels)	46.8%	35.3%	47.3%	55.6%
No awareness of the imminent hazard (no warning)	6.3%	4.3%	35.5%	25.5%
Not specified / no answer	1.0%	0.8%	1.8%	2.6%
Number of valid cases (warning source)	1258	394	448	153
Median of the lead time [hours]	24	24	1	1
Number of valid cases (lead time)	922	305	141	50

To get a clearer picture, Figure 3 shows what kind of emergency measures were undertaken. While residents affected by fluvial flooding in 2013 performed a variety of measures, residents affected in 2016 relied mostly on water pumps. Further, it

440   should be noted that in the case of fluvial floods electricity and natural gas is more often switched off centrally, while those affected by pluvial floods have to take care of it on their own, which poses further risks of electrocution in case a person enters the water.

Overall, the analyses illustrate that residents in areas that are prone to river flooding were provided with better and timely warning information in 2013. Together with their higher level of response knowledge they were capable of performing more

445   emergency measures than residents affected in 2016. Since emergency response seems to be an effective coping strategy for pluvial flooding, particularly due to their relative low water depths (Rözer et al., 2016; Spekkers et al., 2017), our analysis highlights that there is room for improving not only early warning, but also communicating potential measures and adequate behaviour in case of pluvial flooding in general. Table 4 and Figure 3 further reveal that residents affected by dike breaches tend to perform more emergency measures, although they have less knowledge and shorter lead times. The resulting damage

450   (Table 3) shows that this strategy probably only mitigates a small amount of damage. Hence, more studies on the efficacy of emergency measures are needed.

Figure 3: Performed emergency measures before and during the event as reported by households affected by different flood pathways in 2013 and 2016 (multiple answers possible).

455

4.5 Long-term response as coping strategy: performance of property-level flood adaptation BEFORE and AFTER the floods

Besides emergency response in the case of an event, there are various proactive precautionary (or adaptive) measures that can reduce flood losses (e.g. Kreibich et al., 2015; Attems et al., 2020a). Both surveys included questions on the actual and

460   intended implementation of property-level flood adaptation. In particular, respondents were asked to state whether they had implemented a specific measure before or after the event, are planning to do so within the next six months or do not intend to implement that measure. In total, 16 measures were considered, four of which comprised informative measures (search for information about the flood risk or adaptation options, attendance of flood seminars or participation in neighbourhood networks). Another six measures addressed non-structural adaptation (flood-adapted building use, flood-adapted interiors

465   and avoidance of noxious liquids in the cellar, e.g. petrol, paint), which also included measures that improve preparedness (purchase of a water pump or an emergency power generator or existence of an emergency plan and box). Insurance coverage was treated separately. Finally, the implementation of five structural measures was studied (i.e. relocating heating

and electricity, securing heat and oil tanks, improving the flood safety of the building, installing a backflow preventer or water barriers); commonly, structural measures can be implemented by homeowners only.

470 In Table 6 the mean relative implementation per category is presented for the situation before the damaging flood and around nine months later. To calculate the relative implementation, the total count per category was normalized by the count of possible measures per category, i.e. a person who had implemented all five structural measures got the value 1, a person who had only secured the heat and oil tank and implemented a backflow preventer received 0.4 (2/5). The values in Table 6 correspond to the average relative implementation of the measures per category per subsample. It should be noted that only

475 property owners were asked about the five structural measures.

Table 6 reveals that adaptive behaviour before the floods was significantly different between the two flood events. In all categories, i.e. informative, non-structural and structural measures, as well as insurance, people affected in 2013 were better adapted to the flood risk than residents affected in 2016. In most categories, the values for 2013 are around twice as high as in 2016. With regard to the different pathways, there are no differences in the 2016-cases, while in the 2013-samples there's

480 a significant difference with regard to non-structural adaptation and a slight difference in structural adaptation. Hence, people affected by dike breaches in 2013 were less adapted than those affected by river floods (Table 6).

After the flood, the adaptation status and the differences between and within flood events changed considerably revealing a pathway-specific behaviour. Table 6 confirms a boost of information-seeking behaviour in all subsets with, however, a varying degree: people affected by flash floods in 2016 searched most frequently for additional information on flood risk and

485 mitigation options, followed by residents affected by surface water flooding in 2016, dike breaches in 2013 and river floods in 2013 (Table 6).

If we sum up the mean relative implementation of informational precaution before AND after the floods, people affected by dike breaches performed best (52 % mean implementation), followed by river floods in 2013 and flash floods in 2016 (49 % mean implementation each) and surface water floods in 2016 (just 35 % mean implementation). This pattern persists when

490 intended information-seeking behaviour is included (Figure 4) and illustrates that particularly severe flood pathways and impacts trigger information-seeking behaviour.

When it comes to the implementation of non-structural and structural measures or to the conclusion of an insurance policy, the additional mean implementation follows – in principle – a pattern similar to the information-seeking behaviour: residents affected in 2016 implemented the most additional measures, followed by those affected by dike breaches in 2013 and river

495 floods in 2013 (Table 6). This might also be due to the fact, that more people affected by river floods in 2013 had already implemented measures before the flood, so the perceived necessity for further improvement after the flood was not as high as among residents affected in 2016.

Table 6: Property-level adaptation before and after damaging floods as reported by households affected by different flood pathways in 2013 and 2016.

Subsample (Pathway)	River2013	↔	Dike2013	2013 ↔ 2016	Surface2016	↔	Flash2016	Overall
Sample size	1258	—	394	—	448	—	153	2253
Property-level adaptation (long-term) – BEFORE the flood								
People who sought information about the flood hazard or protection options [%]	76.5	.	71.8	****	34.3		32.2	64.3
Of those without flood experience, people who sought information about the flood hazard or protection [%]	65.7		70.7	****	27.1		27.0	51.8
Mean relative implementation of 4 potential informational precautionary measures [%]	39.7		37.6	****	13.8		13.2	32.4
Mean relative implementation of 6 potential non-structural precautionary measures [%]	40.7	***	35.4	****	21.0		19.6	34.4
Mean relative implementation of 5 potential structural precautionary measures [%] (1)	20.0	.	17.6	****	9.5		8.3	16.7
Households that took out insurance [%]	56.9		56.5	****	36.7		35.1	51.4
Property-level adaptation (long-term) – AFTER the flood								
Mean relative additional implementation of 4 potential informational precautionary measures [%]	9.1	****	14.8	****	21.3	****	35.3	14.3
Mean relative additional implementation of 6 potential non-structural precautionary measures [%]	7.6	****	12.1	****	15.8		17.9	10.7
Mean relative additional implementation of 5 potential structural precautionary measures [%] (1)	5.6	**	7.9	****	14.9	.	19.1	8.8
Households that took out insurance after the flood [%]	4.7	***	9.1	****	12.4	****	27.7	8.6

Percentage or means only regarding valid values, i.e. answered entries.

(1) Only among homeowners

*Comparison of subsets or 2013 to 2016 in the middle columns, with P-value ranges from Mann-Whitney-Wilcox or Chi-Square tests represented as: Legend: '****' ≤0.001 '***' ≤0.005 '**' ≤0.01 '*' ≤0.05 '.' ≤0.1 ' ' ≤1*

Figure 4: Cumulative mean relative implementation of adaptation, including measures that were (at the time of the survey) planned to be implemented within the next six months (* surveyed only among homeowners).

510

Considering that the subgroups started at very different levels of adaptation before the events stroke, the cumulative implementation depicted in Figure 4 reveals that non-structural measures are more popular along rivers, i.e. among those affected in 2013. On average, a relative implementation of 50% of a total of six measures is reached, meaning that on average three measures have been implemented per affected household, in contrast to around 40% or 2.4 measures in the

515 case of the 2016-subsamples (Figure 4b). Maybe this is due to a higher risk perception of fluvial floods in contrast to pluvial floods.

Interestingly, the cumulative implementation of structural adaptation measures reaches a similar level across all four flood pathways, though the overall lowest numbers in comparison to the other categories: around nine months after the floods a mean implementation of around 25% (or 1.3 measures) is reported in all four subsamples and inches up to 30% (or 1.5

520 measures) when intended adaptation is included (Figure 4c). This pattern was described before for fluvial floods (Thieken et al., 2007; Kienzler et al., 2015) and pluvial floods (Rözer et al., 2016), where structural measures such as sealing the

basement, relocating heating or electrical utilities to higher stories or changing the heating system or protecting the oil tank had been identified as the least popular measures. Most likely this is due to the higher costs of structural measures and the fact that the property-owner has to implement them.

525 The conclusion of insurance reflects the pattern of the information-seeking behaviour (Table 6, Figure 4d) and highlights that particularly people who experienced severe flood pathways strive for a backstop. In addition, the severity of the flood processes and their impacts might cause a lower appraisal of the efficacy of adaptive measures on the property-level. Therefore, the next section finally looks at perceptions.

4.6 Previously experienced flooding and risk perceptions

530 Since previous flood experience impacts risk perceptions and influences adaptive behaviour (e.g., Bubeck et al., 2012), Table 7 summarizes related outcomes. There are significant differences with regard to previously experienced flooding between and within the events. Most households affected by river floods in 2013, i.e. 64 %, had been affected previously. This percentage is much lower in the subset on dike breaches in 2013 (34 %) as well as on surface water floods in 2016 (29 %), and flash floods (only 21 %; Table 7). As noted by Kienzler et al. (2015), having experienced river floods has 535 considerably changed after the 2002-flood, whilst there is a lower percentage among those affected by pluvial floods, which was also observed by Spekkers et al. (2017), who reported that just 21 % of households surveyed in the city of Münster had been flooded before the severe pluvial flood of July 2014.

However, among all surveyed households, less than 15 % had experienced a flood in the ten years preceding the events that are studied in this paper, with a distinction between the stronger pathways (8 % for 2013-dike breach and 7 % for the 2016- 540 flash flood subsamples) and the low/medium flood pathways (16 % for 2013-river and 17 % for 2016-surface water flood subsamples, see Table 7). Altogether, residents that were affected by flash floods in 2016 were the least experienced with flooding. It is remarkable that the highly significant differences in previously experienced floods between the two events vanish when just the preceding ten years are taken into account, while the differences within the events, i.e. between the different pathways, remain (Table 7).

545 With regard to various perceptions, it is striking that there are no to just small differences between the events and the pathways with regard to perceived self-efficacy and the perceived responsibility of the government (Table 7). A comparison with other regions and data could reveal whether the reported values could be regarded as representative mean perception or as a kind of benchmark. Particularly, self-efficacy is seen as a key component for adaptive behaviour (Bubeck et al., 2013; Poussin et al., 2014) and tends to be lower with regard to flash floods (Table 7), which might be accompanied by heavy 550 structural damage (Laudan et al., 2017).

Average perceived response costs, response efficacy and responsibility of any individual to reduce damage, however, differ between the two events: people affected in 2013 perceived response costs a bit higher than those affected in 2016; this also holds for the perceived efficacy of measures and the responsibility of individuals (Table 7). It is striking that response

efficacy is perceived the lowest by people who were affected by flash floods in 2016, probably highlighting the high

555 velocities and severe impacts on buildings (Table 2 and 3) and indicating the limits of property-level adaptation.

Table 7: Previously experienced flooding and perceptions on risk and property-level adaptation of households affected by different flood pathways in 2013 and 2016.

Subsample (Pathway)	River 2013	↔	Dike 2013	2013 ↔ 2016	Surface 2016	↔	Flash 2016	Overall
Sample size	1258	—	394	—	448	—	153	2253
Previously experienced flooding								
People who experienced at least one previous flood [%]	63.9	****	33.7	****	29.1	.	21.3	48.6
People who experienced a flood in the ten years preceding the damaging event [%]	16.4	****	7.5		16.8	**	7.3	14.3
Perceptions – AFTER the flood								
Mean perceived probability of future floods [Likert-scale from 1 (it is very UNlikely that I will be affected by future floods) to 6 (it is very likely that I will be affected by future floods)]	4.6	****	3.8	****	3.7	***	3.2	4.2
Mean perception of impacts of a future flood LIKE THIS ONE [agreement to the statement "It won't be as bad as in 2013/16" 1: I fully agree to 6: I fully disagree]	4.1	****	3.6	.	4.1	****	3.2	3.9
Mean perceived self-efficacy [agreement to the statement "Personally, I am UNable to implement any of the proposed precautionary measures" 1: I fully agree to 6: I fully disagree]	4.3		4.2		4.5	**	4.0	4.3
Mean perceived costs [agreement to the statement "Private precautionary measures are too expensive" 1: I fully agree to 6: I fully disagree]	2.9		2.9	***	3.3	*	2.9	3.0
Mean perceived response efficacy [agreement to the statement "Private precautionary measures can considerably reduce damage" 1: I fully agree to 6: I fully disagree]	2.6	.	2.8	***	2.7	****	3.3	2.7
Mean perceived responsibility of the government [agreement to the statement "Flood risk reduction is a task of the government, not of the residents" 1: I fully agree to 6: I fully disagree]	3.0	*	2.8	.	3.1		2.9	3.0
Mean perceived responsibility of individuals [agreement to the statement "Everyone is obliged to reduce flood damage as much as possible" 1: I fully agree to 6: I fully disagree]	1.7	*	1.9	****	2.4		2.5	1.9

560

Furthermore, the threat appraisal of future floods differs significantly between and within the events: the perceived probability of future floods is the highest among residents affected by river floods in 2013, followed by dike breaches in
565 2013 and surface water flooding in 2016. Those who were affected by flash floods in 2016 tend to believe that they will not be affected again. This pattern is even more pronounced when a statement on the perception of the impacts of a future flood LIKE THIS ONE was assessed: here the ones who were damaged the most (i.e. by flash floods in 2016 and by dike breaches in 2013, see Table 3) tend to think that impacts comparable to the just experienced are less likely to occur (Table 7). This highlights that it is important to distinguish probability and impacts in threat appraisals as shown by Bubeck et al. (2013).
570 The statement on the perceived impacts of future floods also contains a nuance of denial of the flood risk, which might explain the lower adaptation that is revealed in Figure 4.

5 Conclusions

Based on two surveys among residents in Germany who were affected by flooding in 2013 and 2016, respectively, this paper looked at differences in flood processes, impacts and coping strategies between four flood pathways found in these spatially
575 compound inland flood events. While the socio-economic characteristics did not differ much between the samples (except for income, which can be explained by the spatial patterns of the floods), impacts and coping strategies differed considerably. Based on the detailed quantitative analyses of a broad range of variables presented in section 4, each flood pathway can be characterized qualitatively as shown in Table 8. The following event-based storylines were derived from these findings and can be applied to environments similar to the studied regions.
580

Table 8: Qualitative summary of the flood pathway characteristics, where medium often reflects the averages.

Characteristics	Flood pathways			
	river flood 2013	dike breach 2013	surface water flood 2016	flash flood 2016
Hydraulic flood characteristics	MEDIUM	HIGH	SMALL	HIGH
Financial impacts	MEDIUM	HIGH	SMALL	HIGH
Perceived recovery	MEDIUM	BAD	GOOD	BAD
Warning and emergency response	GOOD	MEDIUM	BAD	BAD
Property-level adaptation before	GOOD	GOOD	BAD	BAD
Property-level adaptation after	MEDIUM	GOOD	BAD	MEDIUM
Flood experience	HIGH	MEDIUM	MEDIUM	LOW
Risk and reponsibility perception	MEDIUM	MEDIUM	MEDIUM	LOW

River floods (2013): The flood processes are characterized by high water levels and long durations of inundations. The financial impacts, recovery and the psychological burden from the flood represent more or less the average of the total data (note that this was the biggest subsample). Most of the residents affected by river floods in 2013 were warned in advance with comparatively long lead times. They were well-prepared, i.e. performed many emergency measures and also showed the highest level of flood adaptation at their property before the flood hit. After the flood they undertook considerable additional adaptation, but Figure 4 reveals that they lost their top position and other subsamples reached the same level, although this group believes on average to be affected again by future floods and also agrees that individuals have to contribute to flood risk reduction. Overall, adaptation of this group could be supported by financial incentives and funds since they perceive response costs as rather high (Table 7). Such costs might also be related to the efforts involved to implement a measure. Therefore, improved consultation and support during implementation as also proposed by Attems et al. (2020b) deserve further attention. Since previously experienced flooding was the highest in this subsample, their level of adaptation after the flood might also indicate a kind of saturation level. This hypothesis, however, needs to be researched in more detail.

Dike breaches (2013): This pathway is characterized by very high water levels, very long durations of inundations and a high frequency of oil contamination. Consequently, the financial impacts are the second highest, repair works at buildings are slow and the psychological burden from the flood is the highest across all four sub-samples. Most of the residents

affected by dike breaches in 2013 were warned in advance with comparatively long lead times. Like those that were affected by river flooding, they performed many emergency measures and showed to be comparatively well-informed about flood hazards and coping options. With regard to structural and non-structural measures, adaptation before the flood was lower than in the river-flood-sample, but they reached a similar level after the flood and a higher level of insurance penetration. Perceptions of flood risk, coping options and responsibilities represent more or less an average behaviour. The fact that losses are very high despite a good responsive and adaptive behaviour indicates the limits of individual adaptation in view of the high hydraulic impacts caused by dike breaches. Insurance serves as a backstop. Overall, this group should be further educated with regard to risks and suitable coping options. Since response time might be limited in case of dike breaches, potential environmental risks due to bursting oil tanks or the release of other harmful substances should receive particular attention. During the last revision of the German Federal Water Act a regulation of oil tanks in (potentially) flood-prone areas was already introduce. Still, more information on effective and suitable property-level adaptation is needed for residents potentially affected by this flood pathway.

Surface water floods (2016): The flood processes are characterized by (very) low water levels and short durations of inundations. Financial impacts and psychological burden from this pathway were the lowest across the sub-samples, while there was a speedy recovery. Threats may occur from high velocities. Most of the residents affected by surface water flooding in 2016 were not warned in advance, lead times were short and knowledge about self-protection was below-average. Hence, people prone to pluvial flooding – this is in general the urban population, since pluvial floods are ubiquitous – should be better informed about potential traps (cellars, subways, cars etc.) and suitable adaptation measures, particularly after events. In comparison to other sub-samples, this group was the least informed and the least insured. Moreover, implementation of non-structural measures was below average – also after the event. Therefore, risk communication on pluvial flooding has in general to be improved and has a good chance to be successful since threat and coping appraisals are well developed and the uptake of measures after the 2016-event was good. Responsibility and feasibility should be clearly communicated and demonstrated by best practise examples. Workshops could serve as a good instrument in this case as they strengthen self-efficacy and protection motivation (Heidenreich et al., 2020).

Flash floods (2016): The flood processes are characterized by (very) high water levels and often (very) high flow velocities which might be accompanied by contamination. These dynamic processes led to the highest financial impacts and a high psychological burden. Recovery was comparable to the dike-breach-sample of 2013, although this group received the highest financial support which might be due to the lumped character of this subsample with cases from just ten municipalities. Like other affected residents in 2016, most of the people in this group were not warned in advance, and if so, lead times were short. Due to potential danger to life caused by flash floods, local forecasting and warning systems should be installed. The preparedness and adaptation before the flood in the subsample is comparable to the surface-water-flood-2016-group. After the flood the information-seeking behaviour was very high, as was the conclusion of insurance policies that serve as a backstop. To strengthen property-level adaptation, risk communication should focus on the efficacy of measures that can also withstand high flow velocities.

Altogether, the study demonstrates that flood hazard characteristics, impacts and coping options differ between and also within compound inland flood events. Hydraulic characteristics and flood impacts are strongly governed by the specific flood pathway, while coping options (short and long term) are more related to the general flood type (i.e., fluvial and pluvial). Hence, the concept of spatially compound events is helpful to understand different flood impacts, but could be strengthened towards coping and adaptive behaviour. The above-mentioned flood pathway-specific recommendations for risk communication and management are a first step in this direction. In addition, we can draw some conclusions that go beyond the studied cases and the German context.

First, the relation between hydraulic forces and impacts strongly support recommendations of developing pathway-specific loss models as done by Vogel et al. (2018) or Mohor et al. (2020, 2021). Research on this is, however, in its infancy. Secondly, to further mitigate damage, risk and crisis communication should distinguish not only flood types, but also pathways highlighting their specific threats, e.g. life-threatening situations during flash floods. Identifying and communicating such threats might better fulfil user needs, as it has been shown that adding impact information or additional descriptions of the threats may provide a clearer picture of the upcoming situation than abstract indications of warning levels (e.g. "strong"), specially to less proficient users (Kox et al., 2018). With regard to flash floods options for local warning and alerting systems should be explored as an option of improving warning and response in small catchments.

Thirdly, it should be noted that experiencing strong flooding caused by dike breaches or flash floods boost precaution, while surface water flooding does not, although the latter can happen almost everywhere. Therefore, modes to communicate and experience flood impacts in a tangible way are particularly important (e.g. exhibitions, storytelling etc.). In addition, the efficacy of emergency and precautionary measures with regard to different pathways needs further research. Finally, people affected by strong pathways such as dike breaches or flash floods (with sediment loads) need special assistance to recover physically and mentally from the impacts; their burden is the highest. Our results indicate that these residents experience limits of their adaptation options.

Author contributions

AT, HK, and MM developed the questionnaires and conducted the surveys. AT and GSM designed the statistical test protocols and GSM mainly carried them out. AT mainly prepared the manuscript with contributions from all co-authors. All authors commented on previous versions of the manuscript. All authors read and approved the final manuscript.

Competing interests

The authors declare that they have no conflict of interest.

Acknowledgements

The two surveys were undertaken within the BMBF-project "Hochwasser 2013" (FKZ: 13N13017) and the DFG Research Training Group "NatRiskChange" (GRK 2043/1), respectively. Funding is gratefully acknowledged, as are additional funds provided by the GeoForschungsZentrum Potsdam and the Deutsche Rückversicherung AG, Düsseldorf, for the data collection. Both surveys were conducted by explorare GmbH, Bielefeld, Germany. We further thank Sarah Kienzler, Jonas Laudan, and Ina Pech for their contributions to the survey design and data processing. The second author would like to thank the German Academic Exchange Service (DAAD) for a scholarship (Graduate School Scholarship Programme, 2017-ID 57320205).

References

Attems, M. S., Thaler, T., Genovese, E., and Fuchs, S.: Implementation of property level flood risk adaptation (PLFRA) measures: choices and decisions, Wiley Interdisciplinary Reviews: Water, 7, e1404, doi:10.1002/wat2.1404, 2020a.

Attems, M. S., Thaler, T., Snel, K. A. W., Davids, P., Hartmann, T., and Fuchs, S.: The influence of tailored risk communication on individual adaptive behaviour, International Journal of Disaster Risk Reduction, 49, 101618, doi:10.1016/j.ijdrr.2020.101618, 2020b.

Bavarian Parliament: Printed matter 17/889, Written enquiry by the representative R. Steinberger BÜNDNIS 90/DIE GRÜNEN, answer by the Bavarian State Ministry of Environment and Consumer Protection, 21st March 2014, 17th legislative period, 2014 (in German).

Bavarian State Government: Hilfsmaßnahmen für die Hochwasserkatastrophe im Mai/Juni 2016, Allgemeines Ministerialblatt, 29, 10, 1632-1641, ;https://www.verkuendung-bayern.de/files/allmbl/2016/10/allmbl-2016-10.pdf#page=1 (last access 6 Sept. 2021), 2016.

Bronstert, A., Agarwal, A., Boessenkool, B., Fischer, M., Heistermann, M., Köhn-Reich, L., Moran, T., and Wendi, D.: The Braunsbach Flashflood of Mai 29th, 2016 – Origin, Pathways and Impacts of an Extreme Hydro-Meteorological Event. Part 1: Meteorological and Hydrological Analysis, Hydrologie und Wasserbewirtschaftung, 61(3), 150–162, doi:10.5675/HyWa_2017,3_1, 2017 (in German).

Bronstert, A., Agarwal, A., Boessenkool, B., Crisologo, I., Fischer, M., Heistermann, M., Köhn-Reich, L., López-Tarazón, J. A., Moran, T., Ozturk, U., Reinhardt-Imjela, C., and Wendi, D.: Forensic hydro-meteorological analysis of an extreme flash flood. The 2016-05-29 event in Braunsbach, SW Germany, Science of the Total Environment, 630, 977–991, 2018.

Bubeck, P., Botzen, W. J. W., Kreibich, H., and Aerts, J. C. J. H.: Detailed insights into the influence of flood-coping appraisals on mitigation behaviour, Global Environmental Change, 23, 1327–1338, doi:10.1016/j.gloenvcha.2013.05.009, 2013.

Bubeck, P., Botzen, W. J. W., and Aerts, J. C. J. H.: A review of risk perceptions and other factors that influence flood mitigation behaviour, Risk Analysis, 32, 1481–1495, 2012.

Cammerer, H. and Thieken, A.: Flood loss reduction due to private precaution. In: Zenz, G. and R. Hornich (Eds.): Urban Flood Risk Management – Approaches to enhance resilience of communities. Proceedings of the International Symposium UFRIM, Graz, 21-23 September 2011, p. 381–386, 2011.

CRED and UN-DRR: Human costs of disasters: an overview of the last 20 years 2000–2019, Report, 2020.

De Bruijn, K., Klijn, F., Ölfert, A., Penning-Rowsell, E., Simm, J., and Wallis, M: Flood risk assessment and flood risk management. FloodSite Report T29-09-01, http://www.floodsite.net/html/partner_area/project_docs/T29_09_01_Guidance_Screen_Version_D29_1_v2_0_P02.pdf (last access, 5 Sept. 2021), 2009.

Demuth, N., Gerlach, N., van der Heijden, S, and Johst, M.: Starkregen und Hochwasser in Rheinland-Pfalz im Mai/Juni 2016, Landesamt für Umwelt Rheinland-Pfalz, 46 pp., http://www.hochwasser-rlp.de/publikationen/bericht_starkregen_hochwasser_juni2016.pdf (last access, 5 Sept. 2021), 2016 (in German).

Destatis – Federal Statistical Office: Wirtschaftsrechnungen: Einkommens- und Verbrauchsstichsprobe – Einkommensverteilung in Deutschland 2013, Fachserie 15, Heft 6, 2018 (in German).

DKKV – Deutsches Komitee Katastrophenvorsorge (Ed.): Lessons Learned – Hochwasservorsorge in Deutschland – Lernen aus der Katastrophe 2002 im Elbegebiet, DKKV-Schriftenreihe 29, Bonn, 2003 (in German).

DKKV (Ed.): Das Hochwasser im Juni 2013 – Bewährungsprobe für das Hochwasserrisikomanagement in Deutschland, DKKV-Schriftenreihe 53, Bonn, 2015 (in German).

Driessen, P. P. J., Hegger, D. L. T., Bakker, M. H. N., Van Rijswick, M. H. F. M. W., and Kundzewicz, Z. W.: Toward more resilient flood risk governance, Ecology and Society, 21, 53, http://www.ecologyandsociety.org/vol21/iss4/art53, 2016.

DWD – Deutscher Wetterdienst (Ed.): Das Hochwasser an Elbe und Donau im Juni 2013, Berichte des Deutschen Wetterdienstes 242, Offenbach, 2013 (in German).

EEA – European Environment Agency: Economic losses from climate-related extremes in Europe, 29 pp., EEA, Copenhagen, Denmark, 2019.

GDV – Gesamtverband der Deutschen Versicherungswirtschaft: Naturgefahrenreport 2016, Berlin, 2016 (in German).

GDV: Naturgefahrenreport 2020 – Serviceteil, Berlin, 2020 (in German).

Gerl, T., Kreibich, H., Franco, G., Marechal, D., and Schröter, K.: A review of flood loss models as basis for harmonization and benchmarking, PLoS ONE, 11, e0159791. doi:10.1371/journal.pone.0159791, 2016.

Heidenreich, A., Masson, T., and Bamberg, S.: Let's talk about flood risk–Evaluating a series of workshops on private flood protection, International Journal of Disaster Risk Reduction, 50, 101880, doi.org/10.1016/j.ijdrr.2020.101880, 2020.

Hübl, J., Heiser, M., Braito, S., Tscharner, S, Kuntner, K., Schraml, K., Falkensteiner, M, and Rabanser, E.: Ereignisdokumentation und Ereignisanalyse Rottal-Inn 2016, IAN Report 180, Vol. 1, 173 pp, BOKU Vienna, 2017 (in German).

Hudson, P., Botzen, W. J., Czajkowski, J., and Kreibich, H.: Moral Hazard in Natural Disaster Insurance Markets: Empirical Evidence from Germany and the United States, Land Economics, 93, 179–208, doi:10.3368/le.93.2.179, 2017.

Hudson, P., de Ruig, L., de Ruiter, M., Kuik, O., Botzen, W., le Den, X., Persson, M., Benoist, A., and Nielsen, C.: Best practices of extreme weather insurance in Europe and directions for a more resilient society, Environmental Hazards, 19, 303–321, doi:10.1080/17477891.2019.1608148, 2020.

IPCC – Intergovernmental Panel on Climate Change: Managing the Risks of Extreme Events and Disasters to Advance Climate Change Adaptation. A Special Report of Working Groups I and II of the Intergovernmental Panel on Climate Change (eds Field, C.B. et al.), Cambridge University Press, Cambridge, UK, and New York, NY, USA, 2012.

Kienzler S., Pech, I., Kreibich, H., Müller, M., and Thieken, A. H.: After the extreme flood in 2002: changes in preparedness, response and recovery of flood-affected residents in Germany between 2005 and 2011, Nat. Hazards Earth Syst. Sci., 15, 505–526, 2015.

Kind, C., Kaiser, T., Riese, M., Bubeck, P., Müggenburg, E., Schüller, L., Fleischmann, R., and Thieken, A.: Vorsorge gegen Starkregenereignisse und Maßnahmen zur wassersensiblen Stadtentwicklung – Analyse des Standes der Starkregenvorsorge in Deutschland und Ableitung zukünftigen Handlungsbedarfs, UBA-Text 55/2019, Dessau, 2019.

Kox, T., Kempf, H., Lüder, C., Hagebdorn, R., and Gerhold, L: Towards user-orientated weather warnings, International Journal of Disaster Risk Reduction, 30, 74–80, doi: https://doi.org/10.1016/j.ijdrr.2018.02.033, 2018.Kreibich, H., Bubeck, P., Van Vliet, M., and De Moel, H.: A review of damage-reducing measures to manage fluvial flood risks in a changing climate, Mitigation and Adaptation Strategies for Global Change, 20, 967–989, 2015.

Kreibich, H., Hudson, P., Merz, B.: Knowing What to Do Substantially Improves the Effectiveness of Flood Early Warning, BAMS, 102(7), E1450-E1463, 2021.

Kreibich, H., Müller, M., Schröter, K., and Thieken, A. H.: New insights into flood warning reception and emergency response by affected parties, Nat. Hazards Earth Syst. Sci., 17, 2075–2092; doi:10.5194/nhess-17-2075-2017, 2017.

Kreibich, H., Petrow, T., Thieken, A. H., Müller, M., and Merz, B.: Consequences of the extreme flood event of August 2002 in the city of Dresden, Germany. In: Sustainable Water Management Solutions for Large Cities (D.A. Savic, M.A. Mariño, H.H.G. Savenije, J.C. Bertoni, Eds.), IAHS Publication, 293, 164–173, 2005.

Laudan, J., Zöller, G., and Thieken, A. H.: Flash floods versus river floods – a comparison of psychological impacts and implications for precautionary behaviour, Nat. Hazards Earth Syst. Sci., 20, 999–1023, doi:10.5194/nhess-20-999-2020, 2020.

Laudan, J., Rözer, V., Sieg, T., Vogel, K., and Thieken, A. H.: Damage assessment in Braunsbach 2016: data collection and analysis for an improved understanding of damaging processes during flash floods, Nat. Hazards Earth Syst. Sci., 17, 2163–2179, doi:10.5194/nhess-17-2163-2017, 2017.

LfU – Bayerisches Landesamt für Umwelt (Ed.): Sturzfluten- und Hochwasserereignisse Mai/Juni 2016 – Wasserwirtschaftlicher Bericht, 2017 (in German).

Masson, T., Bamberg, S., Stricker, M., and Heidenreich, A.: "We can help ourselves": does community resilience buffer against the negative impact of flooding on mental health?, Nat. Hazards Earth Syst. Sci., 19, 2371–2384, https://doi.org/10.5194/nhess-19-2371-2019, 2019.

Mayr, B., Thaler, T., and Hübl, J.: Successful Small-Scale Household Relocation after a Millennial Flood Event in Simbach, Germany 2016, Water, 12(1), 156, 2020.

Merz, B., Elmer, F., Kunz, M., Mühr, B., Schröter, K., and Uhlemann-Elmer, S.: The extreme flood in June 2013 in Germany, Houille Blanche, 5–10, 2014.

Merz, B., Kuhlicke, C., Kunz, M., Pittore, M., Babeyko, A. Y., Bresch, D. N., Domeisen, D. I. V., Feser, F., Koszalka, I., Kreibich, H., Pantillon, F., Parolai, S., Pinto, J. G., Punge, H. J., Rivalta, E., Schröter, K., Strehlow, K., Weisse, R., and Wurpts, A.: Impact Forecasting to Support Emergency Management of Natural Hazards, Reviews of Geophysics, 58, e2020RG000704. doi:10.1029/2020RG000704, 2020.

Mohor, G. S., Hudson, P., and Thieken, A. H.: A comparison of factors driving flood losses in households affected by different flood types, Water Resources Research, 54(6): e2019WR025943, doi:10.1029/2019WR025943, 2020.

Mohor, G. S., Thieken, A. H., and Korup, O.: Residential flood loss estimated from Bayesian multilevel models, Nat. Hazards Earth Syst. Sci., 21, 1599–1614, https://doi.org/10.5194/nhess-21-1599-2021, 2021.

Mühr, B., Daniell., J., Ehmele, F., Kron, A., Dittrich, A., and Kunz, M.: Hochwasser/Überschwemmungen Süddeutschland Mai/Juni 2016. CEDIM-Forensic Disaster Analysis Report No 1, 13 pp., https://www.cedim.kit.edu/download/Hochwasser_Süddeutschland_Report_1.pdf (last access on 5 Sept 2021), 2016 (in German).Munich Re: Topics Geo 2016 – Natural catastrophes 2016 – Analyses, assessments, positions, Munich, 2017.

Neise, T. and Revilla Diez, J.: Adapt, move or surrender? Manufacturing firms' routines and dynamic capabilities on flood risk reduction in coastal cities of Indonesia, International Journal of Disaster Risk Reduction, 33, 332–342, doi:10.1016/j.ijdrr.2018.10.018, 2019.

Noether, G. E.: Introduction to statistics: The nonparametric way, Springer texts in statistics, Springer-Verlag New York, 415 pp., 1991.

Penning-Rowsell, E. C. and Green, C.: New insights into the appraisal of flood-alleviation benefits: (1) Flood damage and flood loss information, J. Chart. Inst. Water Engrs, 14, 347–353, 2000.

Pescaroli G. and Alexander, D.: Understanding Compound, Interconnected, Interacting, and Cascading Risks: A Holistic Framework, Risk Analysis, 38, 2245–2257, 2018.

Piper, D., Kunz, M., Ehmele, F. Mohr, S. Mühr, B., Kron, A. and Daniell, J.: Exceptional sequence of severe thunderstomrs and related flash floods in May and June 2016 in Germany – Part 1: Meteorological background, Nat. Hazards Earth Syst. Sci., 16, 2835–2850, doi:10.5194/nhess-16-2835-2016, 2016.

Poussin, J. K., Botzen, W. J. W., and Aerts, J. C. J. H.: Factors of influence on flood damage mitigation behaviour by households, Environmental Science and Policy, 40, 69–77, doi: 10.1016/j.envsci.2014.01.013, 2014.

R Core Team: R: A language and environment for statistical computing, Version 3.4.2, R Foundation for Statistical Computing, Vienna, Austria, https://www.R-project.org, 2017

Rözer, V., Müller, M., Bubeck, P., Kienzler, S., Thieken, A., Pech, I., Schröter, K., Buchholz, O., and Kreibich, H.: Coping with pluvial floods by private households, Water, 8(7), 304; doi:10.3390/w8070304, 2016.

Sayers, P. B., Hall, J. W., and Meadowcroft, I. C.: Towards risk-based flood hazard management in the UK, Proc. Inst. Civ. Eng. Civ. Eng., 150, 36–42, 2002.

Schröter, K., Kunz, M., Elmer, F., Mühr, B., and Merz, B.: What made the June 2013 flood in Germany an exceptional event? A hydro-meteorological evaluation, Hydrol. Earth Syst. Sci., 19, 309–327, doi:10.5194/hess-19-309-2015, 2015.

800 Shepherd, T.G., Boyd, E., Calel, R.A., Chapman, S.C., Dessai, S., Dima-West, I.M., Fowler, H.J., James, R., Maraun, D., Martius, O., Senior, C.A., Sobel, A.H., Stainforth, D.A., Tett, S.F.B., Trenberth, K.E., van den Hurk, B.J.J.M., Watkins, N.W., Wilby, R.L., and Zenghelis, D.A.: Storylines: an alternative approach to representing uncertainty in physical aspects of climate change, Climatic Change, 151, 555–571, https://doi.org/10.1007/s10584-018-2317-9, 2018.

Sillmann, J., Shepherd, T.G., van den Hurk, B., Hazeleger, W., Martius, O., Slingo, J., and Zscheischler, J.: Event-Based

805 Storylines to Address Climate Risk, Earth's Future, 9, e2020EF001783. https://doi.org/10.1029/2020EF001783, 2021.Spekkers, M., Rözer, V., Thieken, A., ten Veldhuis, M.-C., and Kreibich, H.: A comparative survey of the impacts of extreme rainfall in two international case studies, Nat. Hazards Earth Syst. Sci., 17, 1337–1355, doi:10.5194/nhess-17-1337-2017, 2017.

Surminski, S. and Thieken, A. H.: Promoting flood risk reduction: the role of insurance in Germany and England, Earth's

810 Future, 5, 979–1001, doi:10.1002/2017EF000587, 2017.

Thieken, A., Kreibich, H., Müller, M., and Lamond, J.: Data collection for a better understanding of what causes flood damage – experiences with telephone surveys. In: Flood damage survey and assessment: new insights from research and practice (D. Molinari, S. Menoni, F. Ballio, eds.). AGU, Wiley, ISBN 978-1-119-21792-3, Chapter 7, p. 95–106; doi: 10.1002/9781119217930.ch7, 2017.

815 Thieken, A. H., Kreibich, H., Müller, M., and Merz, B.: Coping with floods: preparedness, response and recovery of flood-affected residents in Germany in 2002, Hydrological Sciences Journal, 52, 1016–1037, 2007.

Thieken, A. H., Müller, M., Kreibich, H., and B. Merz: Flood damage and influencing factors: New insights from the August 2002 flood in Germany, Water Resources Research, 41, W12430, DOI: 101029/2005WR004177, 2005.

Thieken, A. H., Kienzler, S., Kreibich, H., Kuhlicke, C., Kunz, M., Mühr, B., Müller, M., Otto, A., Petrow, T., Pisi, S., and

820 Schröter, K.: Review of the flood risk management system in Germany after the major flood in 2013, Ecology and Society, 21(2), 51, doi:10.5751/ES-08547-210251, 2016a

Thieken, A. H., Bessel, T., Kienzler, S., Kreibich, H., Müller, M., Pisi, S., and Schröter, K.: The flood of June 2013 in Germany: how much do we know about its impacts? Nat. Hazards Earth Syst. Sci., 16, 1519–1540; doi:10.5194/nhess-16-1519-2016, 2016b.

825 Vogel, K., Weise, L., Schröter, K., and Thieken A. H.: Identifying Driving Factors in Flood Damaging Processes Using Graphical Models, Water Resources Research, 54: 8864–8889; DOI: 10.1029/2018WR022858, 2018.

Vogel, K., Öztürk, U., Riemer, A., Laudan, J., Sieg, T., Wendi, D., Agarwal, A., Rözer, V., Korup, O., and Thieken, A.: The Braunsbach Flashflood of Mai 29th, 2016 – Origin, Pathways and Impacts of an Extreme Hydro-Meteorological Event. Part 2: Geomorphological Processes and Damage Analysis, Hydrologie und Wasserbewirtschaftung, 61(3), 163–175,

830   doi:10.5675/HyWa_2017,3_2, 2017 (in German).Zscheischler, J., Martius, O., Westra, S., Bevacqua, E., Raymond, C., Horton, R. M., van den Hurk, B., AghaKouchak, A., Jézéquel, A., Mahecha, M. D., Maraun, D., Ramos, A. M., Ridder, N. N., Thiery W., and Vignotto, E.: A typology of compound weather and climate events, Nature Reviews Earth and Environment, 1, 333–347, doi:10.1038/s43017-020-0060- z, 2020.