

TA Mwakaboko - Mwakaboko GVH - Iponga River





# TA Kyungu/Kilipula - Dumira GVH - Kasoba, Kasisi and Nchowo Rivers



Dumira GVH members during Focus Group Discussion (20/11/2018).



1

Kasisi river meander erosion (2016 houses destroyed). From this point water can burst out and flood south down to Nchowo river.




2

Kasoba coarse sandy shallow river bed. Very destructive (3 houses swept away in 2013). Wide river sand deposition, several courses. In 2015, Kasoba divided into 2 branches. WFP attempts in 2017 to dig and separate the rivers, failed.



3

Nchowo river at M1 road. (20/11/2018).



Legend

schools

FGD

Transect walks

0 0.5 1 1.5 2 km



# TA Kyungu - Mwangdwanga GVH - Nkhomi River



1 Mwangdwanga GVH members during Focus Group Discussion (20/11/2018).



From this point, during floods, water cannot find a way to reach North Rukulu river and floods the entire area around the Stevenson road.


2

Nkomi river culvert built in 2005, filled by sands. (20/11/2018).



1

Flood mark and vegetation planting along Stevenson Road, transformed as river path during floods. (20/11/2018).



3

Flat Nkhomi river profile and proximity to crop fields .





# TA Kyungu - Mwenelupembe GVH - Bwaye River



Mnenelupembe FGD members after community mapping (21/11/2018).




Dry and sandy Bwaye river from M1 bridge (21/11/2018).



Building Damage on 1/02/2018.



M1 Road Damage on 21/11/2018.



Rain gauge of Mwenelupembe GVH.

Participants have been consulted on being recognisable in the photos





# TA Kyungu - Mwangolera GVH - Lwasho River



1  
Mwangolera FGD members  
(22/11/2018).



2  
Dry and sandy Lwasho river course (top) and 2013 historical river bank erosion (bottom) (22/11/2018).



2  
Remain of Flash Flood vegetal debris on trees in Lwasho river course.



# TA Mwirang'ombe - Mwakashunguti GVH - Sabi River

Mwakashunguti GVH members during Focus Group Discussion (23/11/2018).



Sabi river with remains of tree debris and flat flood plain used for Cassava, rice and cattle farming



1


Hilly landscape around Chimbiriri valley and Chibiriri meandering river.



2



3



Participants have been consulted on being recognisable in the photos