Nat. Hazards Earth Syst. Sci. Discuss., 3, C65–C65, 2015 www.nat-hazards-earth-syst-sci-discuss.net/3/C65/2015/ © Author(s) 2015. This work is distributed under the Creative Commons Attribute 3.0 License.



## **NHESSD**

3, C65-C65, 2015

Interactive Comment

## Interactive comment on "Building and design defects observed in the residential sector and the types of damage observed in recent earthquakes in Turkey" by M. Tolga Çöğürcü

## **Anonymous Referee #1**

Received and published: 19 February 2015

Author should be careful not to use the non-English characters. Seismicity and construction defects are discussed with striking examples in the context of earthquake resistant design. Manuscript is a valuable study in terms of clearly be seen to the causes and consequences of constructional defects. Study can be accepted.

Interactive comment on Nat. Hazards Earth Syst. Sci. Discuss., 3, 697, 2015.

Full Screen / Esc

Printer-friendly Version

Interactive Discussion

Discussion Paper

