

Interactive comment on “Using street view imagery for 3D survey of rock slope failures” by Jérémie Voumard et al.

Olga Mavrouli (Referee)

o.c.mavrouli@utwente.nl

Received and published: 4 September 2017

This is a very interesting paper with very useful and innovative ideas and I believe that research towards this direction is promising. However, reading the manuscript I missed a strong and solid part on technical specifications for the methodology that is used and for the quantitative analysis of the results, which is the core and the added value of this work. In that sense, I suggest to the authors, to enrich and support the description of the methodology, providing detailed information on the processes followed and to present a more thorough and detailed analysis of their results, in quantitative terms.

Some specific comments can be found at the attached .pdf file.

[Printer-friendly version](#)

[Discussion paper](#)



Please also note the supplement to this comment:

<https://www.nat-hazards-earth-syst-sci-discuss.net/nhess-2017-49/nhess-2017-49-RC2-supplement.pdf>

Interactive comment on Nat. Hazards Earth Syst. Sci. Discuss., <https://doi.org/10.5194/nhess-2017-49>, 2017.

NHESSD

[Interactive
comment](#)

[Printer-friendly version](#)

[Discussion paper](#)

